

Asbestos in the Home

*Asbestos usage has declined dramatically and in several cases, its usage has been banned. As a result, older homes are more likely to be at risk.



- A Exterior Surfaces**
1. Roof Felt and Shingles
 2. Window Putty
 3. Cement Asbestos Board Siding / Undersheeting

- B Insulation**
1. Vermiculite Insulation
 2. Batt Insulation

- C Flooring**
1. Vinyl Asbestos Flooring Material

- D Interior Surfaces**
1. Sprayed-on Ceiling Material
 2. Textured Paint

- E Boilers, Heating and Piping**
1. Heat Source Covering
 2. Door Gaskets
 3. Duct Lining
 4. Wall Gaskets and Lining

- F Electrical Equipment**
1. Recessed Lighting
 2. Wiring Insulation
 3. Fuse Boxes
 4. Outlets

- G Appliances**
1. Refrigerators / Freezers
 2. Range Hoods
 3. Woodstoves (Heat Reflectors)
 4. Clothes Dryers
- * Not Shown: Dishwashers, Toasters, Slow-cookers, Portable Heaters, Hair Dryers

- H Miscellaneous**
1. Fireplace Logs

- J Automotive**
1. Brake Linings, Gaskets, and Clutch Facings